


PURO WITH END OVERFLOW BATH

OVERFLOW INSTALLATION INSTRUCTIONS


MOUNTING OVERFLOW










MOUNTING THE DRAIN










CONNECTING OVERFLOW and DRAIN










CONNECTING the WASTE WATER SYSTEM and MOUNTING EQUIPMENT SET








LEAKAGE TEST and CONTROL









KALDEWEI

PURO WITH END OVERFLOW BATH


LEG SYSTEM INSTALLATION INSTRUCTIONS




1. Place the bath with its packging upside down.




2. Slot the arm straps of the bath cradle (b) onto the lugs (a) on the base of the bath.



 Push a suitable length of the tensioning belt onto the retaining bolt (a), engage the threaded hook (c) and tighten by hand using the nut on the base.



4. Turn over bath, align with the help of a spirit level by turning the screw and tighten the locknut (d).



Baths might also be mounted with bath anchors (not included in the scope of delivery).

