



- Compressor Contactor 1
- Electronic Overload 1
- Compressor Winding Temperature Sensors
- Compressor Contactor 2
- Electronic Overload 2
- INT 69 TML Protection Module
- Condenser Fan Contactor 3 & 4 & 5
- Electronic Overload Coil 1 & 2
- Crankcase Heater
- Compressor Contactor 1
- PWS Time Delay 0.8 Sec
- Compressor Contactor 2
- Fan Motor Contactor 3
- Fan Motor Contactor 4
- Fan Motor Contactor 5

APPROVED
 By Roger Stringer at 12:46 pm, Sep 04, 2020

LEGEND	
Field Wiring	----
Terminal Number	②
Connection Number	④
Fan Speed	△

WARNING
 THE ELECTRICAL CONNECTION OF THIS UNIT MUST BE PERFORMED BY QUALIFIED PERSONNEL AND MUST COMPLY WITH LOCAL ELECTRICAL STANDARDS

SHT PWS Series with INT-69 TML			ACTROL™
Diagram for 3 Phase 415 Volt 50 Hz			
Drawn By	Checked by : R. Stringer	7684629 Index -	Last Update 26 Aug 2020