




WARNING

THE ELECTRICAL CONNECTION OF THIS UNIT
MUST BE PERFORMED BY QUALIFIED
PERSONNEL AND MUST COMPLY WITH LOCAL
ELECTRICAL STANDARDS

SHR (S) PWS Series

Diagram for 3 Phase 415 Volt 50 Hz

Drawn By

Checked by : R. Stringer

7684503 Index B

Last Update 28 Aug 2019

Distributed by
ACTROL
Your best solution...