



Installation Instructions

Important

Outlets must be installed to the requirements of AS/NZS 3500 by a qualified plumber.



Max Continuous Working Pressure 1000 Kpa. Max Continuous Working temperature 65 Deg.



Avoid prolonged exposure to any chemical solution containing chlorides or acids. Surface damage caused by acids will void warranty.

Note: Ensure water supply lines are flushed prior to installation.

Solus Bath Outlet 210mm

pcsh

Installation

- 1. Ensure adequate threaded nipple is exposed.
- 2. If required cut threaded nipple to length suit spout.
- 3. Apply thread tape to threaded nipple.
- 4. Screw on outlet.
- 5. Do not over tighten.

Note: Ensure spout is aligned correctly

6. Turn on water supply and check for any leaks.

Drawing



Care Details

We recommend the use of soapy water or approved cleaners. This product should not be cleaned with abrasive materials. Damage caused by any improper treatment is not covered by the product warranty - refer to Warranty Conditions on the last page.

Plumbers, please ensure a copy of the installation instruction is left with the end user for future reference.

