PLUMBERS INSTALLATION INSTRUCTIONS

Important Information

- * Not suitable for gravity feed systems.
- * All pipework must be thoroughly flushed prior to installation.

Installation

- 1) Check that threaded nipple (1) is the correct length, as shown. Apply thread tape to the thread.
- Screw the inlet of the bath outlet (2) onto the threaded nipple (1) and position as required, taking care not to damage the decorative finish. DO NOT OVERTIGHTEN.

IMPORTANT

Pressure & Temperature Requirements.

- Hot and cold water inlet pressures should be equal.
- Static inlet pressure range : 150 -1000 kPa
 New Regulation :-500 kPa maximum static pressure
 at any outlet within a building.
 (Ref. AS/NZS 3500.1-2003, Clause 3.3.4)
- Maximum hot water temperature : 80°C.

